





A Unit of AMERON GLOBAL, INC.



# 2009 TECHNICAL PUBLICATIONS INDEXES

March 17, 2009





## TECHNICAL MANUAL INDEX

CMM NUMBER	REVISION	DATE	PART NUMBER DESCRIPTION	CUSTOMER AIRCRAFT MODEL
26-20-01	2	3/15/02	Lavatory Fire Extinguisher with Pressure Switch P/N 21100 Series	Boeing Models 737-300, 737-400, 737-800, 747-200B, 747-200C, 747-300, 747-400, 767-300, MD-11
26-20-02	5	5/1/02	Water Solution Fire Extinguisher, Hand-Held, P/N M892480	Various
26-20-03	---	10/15/02	Water Solution Fire Extinguisher, Hand-Held, P/N M892480-SS	Various
26-22-01	---	---	OBSOLETE	---
26-22-02	5	2/2/09	Hermetic Sealed and Metal-to-Metal Sealed Fire Extinguishers	Various
26-22-03	3	11/30/06	Manifold Valve Body Assembly Fire Extinguishers	Various
26-22-05	1	3/16/09	Fire Extinguisher P/N M57331-009	Shorts Bros. Models SD3-30, SD3-60, SD3-SHERPA, SD3-60SHERPA
52-10-02	5	9/15/03	Reservoir Assembly Door Emergency Power P/N 40400-2 BAC SPEC. No. 60B10003	Boeing Models 747-100, 747-200B, 747-200C 747-200F, 747-400, 757-200
52-10-04	0	10/30/08	Reservoir Assembly Emergency Air P/N PR02400-1	Learjet Model 60



## SUPPLEMENT INDEX

CMM NUMBER	REVISION	DATE	CMM	CUSTOMER AIRCRAFT MODEL
22400-2	0	12/15/01	26-22-02	Aerospatiale Super Puma A332 MK2
23500-1	2	3/15/03	26-22-02	MD Helicopter, MD 900 and MD 902
24200-8	0	2/2/09	26-22-02	Duncan, Various
24600-1	1	3/15/03	26-22-02	Fairchild, Metroliner
24600-2	2	3/15/04	26-22-02	Fairchild, Metroliner
25300-1	1	3/15/03	26-22-03	Duncan, Various
25700-1	1	7/1/03	26-22-02	Eurocopter, Super Puma
25700-2	1	7/1/03	26-22-02	Eurocopter, Super Puma
25700-3	0	3/1/03	26-22-02	Eurocopter, Super Puma
25700-4	0	3/1/03	26-22-02	Eurocopter, Super Puma
27300-1	3	2/2/09	26-22-02	Agusta, A109
28200-1	0	3/15/02	26-22-02	Bell Helicopter V-22
29800-1	1	1/14/02	26-22-02	Sikorsky S 92
50700-1	1	4/15/99	26-22-02	Fairchild, Metroliner
50800-1	0	10/1/01	26-22-02	Bell Helicopter BA609
51500-103	0	7/15/00	26-22-02	Bell Helicopter 427
51500-105	0	7/15/00	26-22-02	Bell Helicopter 427
51600-2	3	7/1/03	26-22-02	Learjet 45 (Honeywell)
51800-1	0	11/1/02	26-22-02	Bell Helicopter H-1
51900-1	1	2/15/04	26-22-04	Sikorsky S 76
53100-1	0	2/2/09	26-22-02	Bell Helicopter BA609
M811456	4	3/11/09	26-22-02	FalconJet



## SERVICE BULETIN INDEX

NUMBER	REVISION	DATE	SUPPLEMENT AND CMM	SUBJECT
M30903870-26-1	0	10/30/09	---	Electrical connector will not connect to aircraft plug.
<b>ALERT</b>				
21100-26-1	0	2/28/00	26-20-01	Discharge caps installed improperly.
25700-26-2	0	3/1/03	26-22-02	Swivel nuts on discharge outlets cracking.
51600-26-2	0	6/22/06	26-22-02	Swivel nuts on discharge outlets cracking.
ASB-26-2	0	11/28/05	---	Possible leak path through cartridge body when actuated.
ASB-26-3	0	3/31/08	26-20-02	Rubber seal leakage on check valve assembly.
ASB-26-5	1	9/18/08	26-22-02	Incorrect wiring in cartridges.



## SERVICE INFORMATION LETTER

NUMBER	REVISION	DATE	SUBJECT
26-01	2	3/15/01	Lavatory fire extinguisher P/N M30100022-3 and P/N M30100022-16. Reference CMM 26-20-01.
26-02	0	11/30/98	FAA – PMA Component Parts, PMA Supplement 9.
26-03	1	4/30/99	Solid State Temperature Compensated Pressure Switch P/N M35071500 Removal and Installation. Reference CMM 26-22-04.
26-04	0	3/30/99	Fire extinguisher P/N 50700-1, replace filler valve P/N 20440-1 with filler valve P/N 20440-2. Reference CMM Supplement 50700-1.
26-06	5	10/15/01	FAA – PMA Cartridges (o-ring) safety of handling and bridgewire test, PMA Supplement 10.
26-07	0	3/30/00	FAA – PMA Cartridges (hermetic), PMA Supplements 16, 18, and 20.
26-08	9	8/30/03	FAA – PMA Cartridges (hermetic) safety of handling and bridgewire test.
26-09	0	7/15/00	Test tolerances for tire gauges P/N's 10000-1, 10100-1, 10200-2, 10300-3, and 13600-1.
26-11	0	7/15/01	Portable water solution fire extinguisher P/N M892480. Reference CMM 26-20-02.
26-13	0	1/30/02	Disposal procedure for MASS Systems cartridges.
26-14	0	12/15/01	Fire extinguisher P/N M811456
26-16	5	8/1/06	Cartridge packing specifications
26-18	0	5/15/03	Alodine coating on discharge outlets P/N 25720-1.
26-19	0	11/1/05	Cartridges 30600-29, -31 & -45 have increased safety of handling.
26-21	0	1/24/08	Cartridge M53000399-1 has increased safety of handling.
26-22	1	2/26/08	Removed cartridge CT00150-1 as a Cutter, Cable, Explosive.
26-23	0	2/26/08	Proper storage & handling of cartridges CT00500-1, CT00600-1 & CT01200-1.



## **SERVICE INFORMATION LETTER (CONT'D)**

<b>NUMBER</b>	<b>REVISION</b>	<b>DATE</b>	<b>SUBJECT</b>
52-01	1	10/15/01	Emergency Power Reservoir Assembly P/N 40400-2, PMA Supplement 19.
52-02	1	3/15/02	Emergency Power Reservoir Assembly P/N 42500-3, PMA Supplement 22.
52-03	0	3/15/02	Reservoir P/N 41500-3 and P/N 41500-4.
52-04	1	9/15/03	Cylinder, Floatation P/N 44000-1
52-05	0	9/15/03	Emergency Power Reservoir Assembly P/N 40400-2, replace gray anodized actuator assembly with gold anodized actuator assembly.